



SUNSHINE COAST REGIONAL DISTRICT

Question and Answers #2

Project no

Title: Halfmoon Bay Fire Command Truck

Date: August 14th, 2025

Item No.1

With regards to siren control module (Cencom core) specification in appendix A:

Question: What type of Cencom Core siren control module would you like to use with the system?

Answer: We would request the control module to be exact or similar to our current duty vehicle. Please see attached figures in the appendix of this document.

Item No.2

With regards to the Whelen ION Series & Hella Here Flex LED Turn Signals, Headlights, and Taillights specification in appendix A:

Question: Where would you like the ION Series Lights mounted, and should they be Red/White as well?

Answer: Front grille, side body panels, rear bumper. Red and white.

Item No.3

With regards to the installation of Two Customer-Supplied Mobile Radios specification in appendix A.

Question: Will a replacement console be provided by the SCRD that accommodates the radios and siren controller, or should we source one for you?

Answer: We would request the console to be supplied by the bidder similar to our current duty vehicle. Please see attached figures in the appendix of this document.

Item No.4

With regards to the installation of Two Customer-Supplied Mobile Radios specification in appendix A.

Question: What kind of radios are they (VHF, UHF, etc.) and how do they plan to be utilized in the field?

Answer: VHF radios. HBFD will purchase from BC Communications who will supply to bidder.

Item no. 5

With regards to the installation of Setina brush bar with emergency lighting and two siren speakers mounted on front bumper specification in appendix A.

Question: Are you requesting a total of four lights – two on the front and one on each side? Should these lights be Red/White?

Answer: Yes, to all

Item no. 6

With regards to Lighting Integration with Vehicle Signals specification in appendix A.

Question: Would you like the system configured such that the white lights automatically turn off when the vehicle is placed in park?

Answer: Not necessary

Appendix:



Figure 1



Figure 2