



# SUNSHINE COAST REGIONAL DISTRICT

## Question and Answers #2

Request for Proposal No. 2337014

Exposed Intake Line Trestles Rehabilitation

**Date: September 9, 2023**

### **Item No.1**

**Question:** What schedule of pipe should be used for hand rail?

**Answer:** Schedule 40 pipe.

### **Item No.2**

**Question:** Will handrails need any weld inspections or welding procedure?

**Answer:** No, but all welding will comply with ISO 15610:2023

### **Item No.3**

**Question:** We would like to propose the use of Pronto - 11 instead of Masterflow 928. Please see the attached product data sheet.

**Answer:** Please comply with the stated Masterflow 928 product as specified by the Structural engineer.

### **Item No.4**

**Question:** Are the cross bracing on the trestles to be painted? Tender form only calls for upright columns to be painted currently.

**Answer:** If the cross bracing is not stainless steel material, the cross bracing must be primed and painted.